Week	#ITS	
WK14-r99096	210101620	Fix:L2TP Wizward
	210200733	Fix:Email Security daemon issue
	210100444	Fix:Warning Picture doesn't appear if Content Filter and SSL inspection is enabled
	210200280	Fix:contfltd dead when customer enables SSL inspection
	201000214	Fix:Windows lost IPv6 route to the Internet
	210200627	Fix:MSTP from Aruba switch
	210200863	Fix:Device HA failover issue when configure virtual server load balance
	210200627	Fix:admin password issue after firmware upgrade
	210300997	Fix:Update DNS root hint file
	210300954	Fix:USG Series; Anti-Spam setting with "=" in x-header
	201200826	Fix:startup config will not load
	210301305	Fix:Correct CLI output typo wording
	210301407	Fix:ZyWALL 1100 / CNC firmware
	210301272	Fix:Can't add new interface into bridge with virtual interface
	210200573 210200579	Fix:Issue with video conferencing
	210301549	Fix:Session Monitor sorting issue
	190200518	Fix:Streamer Connection failed
	210301528	Fix:Facebook Wi-Fi is not launched in USG1100
	210400219	Fix: RADIUS Users cannot change EZ to Expert mode
	210400228	Fix:ATP500 / HA Mode / Config Change (VLAN) requires reboot to function
	210400211	Fix:SMS 2FA for SSL VPN requested for every file access
	[CVE-2020-1971]	Fix: Fix OpenSSL Vulnerability.
	210101673	Fix:Cannot set the lifetime value of 1 year on certificates
	201001362	Fix:Policy route does not work on specific situation.
	210101017	Fix:ATP200 periodical self0restart due to memory leaking.
	210101205	Fix:Editing of a bridge interface is not possible without restarting.
	210101331 210200068	Fix:Inconsistent Remaining time for billing period.
	210200099	Fix:Multi-leagual issue in IP Reputation > External Black List
	210100862	Fix:ATP200 reboot due to memory increase
	201200161	Fix:Possible issue with CSR generation.